



## HMFX WELDING INSTRUCTIONS

1. Tack weld on the front side, centring the frame onto the cut-out hole.  
Same as step 2 of standard welding instructions.



|                        |   |                            |            |
|------------------------|---|----------------------------|------------|
| Minimum hole dimension | = | (external HMFX dimensions) | less 110mm |
| Maximum hole dimension | = | (external HMFX dimensions) | less 10mm  |

2. Grind off weld tacks before start filled weld. Weld runs should not start or stop at a tack weld but should run over a tack.

Follow same welding sequence for correct procedure.


The interpass temperature should not exceed 200°C for mild steel and aluminium and 150°C for stainless steel.

This welding throat should not exceed following values:

$$\begin{aligned} T > 7\text{mm} & \quad a = 5\text{mm} \\ T \leq 7\text{mm} & \quad a = 4\text{mm} \end{aligned}$$

■ Max Run Length

|   |                 |        |
|---|-----------------|--------|
| { | Mild Steel      | 200 mm |
|   | Stainless Steel | 150 mm |
|   | Aluminium       | 200 mm |



$$\text{Heat Input (KJ/mm)} = \frac{V \cdot I \cdot \eta}{\text{vel} \cdot 1000} \quad \eta = \begin{cases} 1 & \text{SMAW} \\ 0,8 & \text{GMAW / FCAW} \\ 0,6 & \text{GTAW} \end{cases}$$

$V = \text{volts} / I = \text{amperes} / \text{vel} = \text{mm/s}$

|          | Máx. Heat Input (KJ/mm) |                 |           |
|----------|-------------------------|-----------------|-----------|
|          | Mild Steel              | Stainless Steel | Aluminium |
| a = 4 mm | 1,2                     | 1,1             | 2         |
| a = 5 mm | 1,4                     | 1,1             | 2         |