

◆→ EMC CABLE SHEATH REMOVE TOOL

This re-usable tool is designed to remove the cable sheath with precision and without damaging the cable screen.



| Description | Cable diameter | |
|--------------------------------|----------------|--------------|
| | Minimum (mm) | Maximum (mm) |
| Cable sheath remove tool 972/A | 4 | 22 |
| Cable sheath remove tool 972/B | 6 | 32 |
| Cable sheath remove tool 972/C | 10 | 64 |

◆→ EMC COPPER TAPE

Hawke Copper Tape (Ref. 950) is used in EMC systems to fill the gap between the cable screen and the EMC HF block after cable sheath has been removed.

It provides a high conductive path from cable screen to earth.

